Compatibility to Microsoft Windows 7 Updates Application Run Time Problems

Technical Information

Products:

- R&S®EMC32
- R&S®AMS32
- R&S®WMS32

Rohde & Schwarz EMC Software Development has recognized that particular Microsoft Windows 7 updates have modified the function of the Windows Smart Card Service leading to the problem that our measurement applications listed above will stop working.

This technical information lists the known Microsoft Windows 7 updates and how to fix it.

Note:





Table of Contents

1	Problem Description	3
1.1	R&S EMC32 / AMS32 / WMS32 has stopped working	3
1.2	List of known Windows Updates	.3
1.3	Further Information	.3
2	Solution	4

1 Problem Description

1.1 R&S EMC32 / AMS32 / WMS32 has stopped working

After installing Microsoft Windows 7 updates above mentioned application may sporadically stop working either on startup or during run time with this message.



1.2 List of known Windows Updates

We have detected that these three Windows Updates for Windows 7 cause modifications on the Windows smart card services which make EMC32 instable (sporadic crash on start or during run time):

2018-01 Preview of Monthly Quality Rollup for Windows 7 for x64-based Systems (KB4057400)

2018-02 Security Monthly Quality Rollup for Windows 7 for x64-based Systems (KB4074598)

2018-02 Preview of Monthly Quality Rollup for Windows 7 for x64-based Systems (KB4075211)

For further information on these updates go to

https://www.catalog.update.microsoft.com/Home.aspx

1.3 Further Information

Microsoft Windows 10 installations of above applications are not affected.

2 Solution

Download and install the Microsoft Update KB4091290 for your system.

2018-03 Update for Windows 7 for x64-based Systems (KB4091290)

https://www.catalog.update.microsoft.com/Search.aspx?q=KB4091290

Download Link for X64 system.

 $windows 6.1-kb 4091290-x 64_ad 76507f 49015fc 85b 1dfb 3c062175135bd 7b413.msu$

Important:

Install first all pending Windows Updates like the "2018-02 Security Monthly Quality Rollup for Windows 7 for x64-based Systems (KB4074598)" before installing this update KB4091290.

If this installation order is not observed the issue is not solved!

Rohde & Schwarz

The Rohde & Schwarz electronics group offers innovative solutions in the following business fields: test and measurement, broadcast and media, secure communications, cybersecurity, radiomonitoring and radiolocation. Founded more than 80 years ago, this independent company has an extensive sales and service network and is present in more than 70 countries.

The electronics group is among the world market leaders in its established business fields. The company is headquartered in Munich, Germany. It also has regional headquarters in Singapore and Columbia, Maryland, USA, to manage its operations in these regions.

Regional contact

Europe, Africa, Middle East +49 89 4129 12345 customersupport@rohde-schwarz.com

North America 1 888 TEST RSA (1 888 837 87 72) customer.support@rsa.rohde-schwarz.com

Latin America +1 410 910 79 88 customersupport.la@rohde-schwarz.com

Asia Pacific +65 65 13 04 88 customersupport.asia@rohde-schwarz.com

China +86 800 810 82 28 |+86 400 650 58 96 customersupport.china@rohde-schwarz.com

Sustainable product design

- Environmental compatibility and eco-footprint
- Energy efficiency and low emissions
- Longevity and optimized total cost of ownership

Certified Quality Management ISO 9001

Certified Environmental Management ISO 14001

This and the supplied programs may only be used subject to the conditions of use set forth in the download area of the Rohde & Schwarz website.

Version 1.00 | R&Application Run Time Problems

 $R\&S^{\circledcirc}$ is a registered trademark of Rohde & Schwarz GmbH & Co. KG; Trade names are trademarks of the owners.



Rohde & Schwarz GmbH & Co. KG

Mühldorfstraße 15 | 81671 Munich, Germany

Phone + 49 89 4129 - 0 | Fax + 49 89 4129 – 13777

www.rohde-schwarz.com